

**INDEX****Un-Starred Question No. \*103****Listed on 10.08.2022**

<b>Sr. No.</b>	<b>Particulars</b>	<b>Page No.</b>
1.	Reply (in English)	1
2.	Reply (in Hindi)	2

**DETAILS OF SCHOOL BUILDINGS**

**103    SH. JAGBIR SINGH MALIK (Gohana):**

Will the Education Minister be pleased to state whether the building of all schools of Gohana Assembly Constituency are safe as per PWD norms; if not, the details of the schools having unsafe buildings together with the details of Schools having insufficient rooms?

**REPLY**

**SH. KANWAR PAL, EDUCATION MINISTER**

Yes Sir,

Out of 86 Schools 74 School buildings are safe as per P.W.D. norms and only 12 Schools have unsafe buildings and there are 5 Schools which have insufficient class rooms in Gohana Assembly Constituency. The list is as under:-

<b>SR. NO</b>	<b>SCHOOL WITH UNSAFE BUILDINGS</b>	
1	GHS	KATWAL
2	GGPS	JASRANA
3	GSSS	ANWALI
4	GPS	PUTHI
5	GPS	RUKHI
6	GPS	KAILANA
7	GPS	RAMGARH
8	GPS	WAZIRPURA
9	GPS	TIHAR MALIK
10	GPS	KHANPUR KALAN
11	GPS	KHANPUR KALAN (V.D)
12	GHS	KASANDI

<b>Sr. No</b>	<b>School with insufficient rooms</b>		<b>Requirement of Rooms</b>
1	GPS	JASRANA	2
2	GPS	RABHRA	3
3	GSSS	GARHI U.K	4
4	GSSS	LATH	1
5	GMS	KHANPUR (V.D)	1

-----

विद्यालय भवनों का ब्यौरा

103 श्री जगबीर सिंह मलिक (गोहाना):

क्या शिक्षा मंत्री कृपया बताएं कि क्या गोहाना विधानसभा निर्वाचनक्षेत्र के सभी विद्यालयों के भवन लोक निर्माण विभाग के मानदण्डों के अनुसार सुरक्षित हैं; यदि नहीं, तो असुरक्षित भवनों वाले विद्यालयों का ब्यौरा क्या है तथा अपर्याप्त कमरों वाले विद्यालय का ब्यौरा क्या है ?

उत्तर

श्री कंवर पाल, शिक्षा मंत्री

(क) हां, श्रीमान जी

गोहाना विधानसभा क्षेत्र में 86 विद्यालय भवनों में से 74 विद्यालय लोक निर्माण विभाग मानदंड के अनुसार सुरक्षित हैं; केवल 12 विद्यालयों के भवन असुरक्षित हैं और 5 विद्यालयों में अपर्याप्त कक्षा-कक्ष हैं। सूचि निम्न प्रकार है:-

क्रमांक	असुरक्षित भवनों वाले विद्यालय	
1.	रा0उ0वि0	कटवाल
2.	रा0क0प्रा0पा0	जसराना
3.	रा0व0मा0वि0	ऑवली
4	रा0प्रा0पा0	पुठी
5	रा0प्रा0पा0	रुखी
6	रा0प्रा0पा0	केलाना
7	रा0प्रा0पा0	रामगढ
8	रा0प्रा0पा0	वजीरपुरा
9	रा0प्रा0पा0	तिहाड़ मलिक
10	रा0प्रा0पा0	खानपुर कला
11	रा0प्रा0पा0	खानपुर कलां (वी0डी0)
12	रा0उ0वि0	कासंडी

क्रमांक	अपर्याप्त कक्षा-कक्ष वाले विद्यालय	कक्षा-कक्ष की आवश्यकता
1	रा0प्रा0पा0	जसराना
2	रा0प्रा0पा0	रबहड़ा
3	रा0व0मा0वि0	गढी यू0के0
4	रा0व0मा0वि0	लाठ
5	रा0मा0वि0	खानपुर (वी0डी0)

-----